

Sample Only Real rei

Check-in

Check-in Details Property	Example address
Property Manager	Open Rent
Date of Check-in	15/05/2014
Management Status	Let Only
Photo	
Tenant Happy	Yes
Tenant Comments	(%C)

Tenants —————		
Teriarits		
Name	tenant's name	
Mobile	tenant's phone number	
Other Phone		
Email	,,0	
	10	

Key Details Key Description (all keys)	2x communal door fobs. 2x front door Chubb type keys. 2x front door small Chubb keys. 2x window keys and 1x garage key.
Notes	
Are All Fobs Working?	Yes
Entrance Codes	N/A
Alarm Codes	N/A
Keys Photo	

Parking Parking		
Faiking		
Parking Available?	No	
r arking / wallable:	140	
Number of Chases		
Number of Spaces		

Cleaning

Is Cleaning Needed? No

Grout Details

Grout Clean Yes

Mildly discoloured. Notes

Photos:



Condensation Details

Signs of Condensation No

Notes

Sample Only Real Replacement of the Na

Utilities		
Item	Details	Photo
Gas Meter	Reading: 16464 Serial Number: 1234	
Electric Meter	Reading: Rate 1: 08446 / Rate 2: 20844 Serial Number: abcd	Successful Wall Short State Suited State Displicat S
Water Meter	Reading: Could not locate	
Stopcock Location	Kitchen cupboard	
Fusebox Location	Kitchen cupboard	
Comments	Gas meter is locate behind kitchen unit in corner	

Contacts

Concierge/Caretaker/Management contact details

Tenant Requests

Request For tenant to place some items of furniture in garage.